

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	price
P001	12.118	84 fastener, outer door skin to reinforcement at belt (6) (does one door)	\$ 6.00
P002	2.736	84-88 screw, headlight ring (8) (SS) (does both headlights)	\$ 3.00
P003	14.686	84-88 screw, armrest (does both doors) (6)	\$ 3.00
P004	2.341	84-88 bolt, battery cable terminal (2)	\$ 5.00
P005	12.118	84-88 rivet, drive type, body side molding (2)	\$ 1.00
P006	12.118	84-88 rivet, push in type, body side molding (3)	\$ 2.00
P007	12.895	84-88 screw, nylon encapsulated torx head, door skin to frame (does one door) (7)	\$ 10.00
P008	10.485	84-88 actuator, power door lock	n/a
P009	2.188	84-88 repair harness, ignition switch	\$ 15.00
P010	2.188	84-88 lock, ignition, chrome w/ 2 keys and retaining screw	\$ 26.00
P011	2.188	84-87 lock, ignition, black w/ 2 keys and retaining screw	\$ 29.00
P012	12.248	84-88 (P37) lock, deck lid w/ 2 keys, 2 shafts and a return spring	\$ 28.00
P013	10.470	84-88 lock set, door, bright cover-black shutter (2 locks, 2 clips, 2 keys)	n/a
P014	2.187	84-86 key, ignition w/ black molded boot "GM" (50A groove)	\$ 3.00
P015	2.187	84-86 key, deck w/ black molded boot "GM" (51B groove)	\$ 3.00
P016	2.187	84-86 keys, ignition and deck w/ black molded boot "GM"	\$ 6.00
P017	2.187	87-88 key, ignition w/ black molded boot "GM" (54C groove)	\$ 3.00
P018	2.187	87-88 key, deck w/ black molded boot "GM" (55D groove)	\$ 3.00
P019	2.187	87-88 keys, ignition and deck w/ black molded boot "GM"	\$ 6.00
P020	2.187	84-88 key boot, rectangular for ignition key (GM)	\$ 1.00
P021	2.187	84-88 key boot, oval for deck key "GM"	\$ 1.00
P022	2.187	84-88 key boot, 1 rectangular, 1 oval "GM"	\$ 2.00
P023	8.921	86-88 nut, "GT" on rear panel (2)	\$ 1.00
P024	7.832	87-88 (P37) 88 Formula nut, "PONTIAC" on rear panel (3)	\$ 1.50
P025	10.716	84-88 stop, door window	\$ 4.00
P026	14.686	84 nut, arm rest to hanger plate (2)	\$ 3.00
P027	12.940	84-88 screw, air intake grille (drivers side quarter panel) (2)	\$ 2.50
P028	12.940	84-88 screw and nut air intake grille (drivers side quarter panel) (4 of ea)	\$ 4.50
P029	12.800	84-88 retainer, cowl vent panel (2)	\$ 4.00
P030	10.783	84-88 actuator, power window	\$115.00
P031	10.527	84-88 clip, outside door handle rod to lock	\$ 1.00
P032	10.466	84-88 pins and bushings, door hinge (does 1 door)	\$ 6.00
P033	10.466	84-88 pins and bushings, door hinge (does both doors)	\$ 12.00
P034	9.667	84-88 retainer, radio (nylon pin in back of radio)	\$ 2.00
P035	9.667	84-88 nut, front radio speaker (does both speakers) (8)	\$ 4.00
P036	2.535	86-88 repair harness, low freon pressure switch (at A/C compressor)	\$ 14.00
P037	2.535	87-88 repair harness, throttle body injector	\$ 12.00
P038	2.535	88 repair harness, oil pressure switch	\$ 24.00
P039	2.535	84-88 repair harness, MAP sensor	\$ 15.00
P040	2.535	84-88 repair harness, idle air control valve	\$ 18.00
P041	2.535	87-88 repair harness, voltage regulator module	\$ 19.00
P042	2.535	87-88 repair harness, ignition distributor module	\$ 16.00
P043	2.535	85-86 repair harness, cooling fan temperature switch	\$ 18.00
P044	2.535	85-88 repair harness, A/C pressure switch	\$ 15.00
P045	2.737	84-88 kit, headlight adjustment (does 1 headlight) (2 screws, 2 nuts, 1 spring)	\$ 5.00
P046	2.728	84-88 kit, headlight bezel mounting (8)	\$ 4.00
P047	2.585	84-88 screw, parking light lens (does both lights) (SS) (4)	\$ 3.00
P048	2.585	84-88 screw and nut, parking light lens (does both lights) (8)	\$ 5.00
P049	2.714	84-88 socket, license plate light	\$ 11.00
P050	2.694	84-88 socket, tail, turn and stop light	\$ 14.00

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	price
P051	2.596	84-88 <b>socket</b> , park / turn signal light	\$ 11.00
P052	2.575	84-88 <b>socket</b> , side marker light	\$ 11.00
P053	1.453	85-86 (2.8) <b>plug</b> , oil drain	\$ 2.50
P054	1.453	84-87 (2.5), 87-88 (2.8), <b>plug</b> , oil drain	\$ 3.00
P055	11.561	84-88 <b>nut</b> , seat track to floor (does 1 seat) (4)	\$ 4.00
P056	2.760	84-88 <b>nut</b> , headlight assembly to body (does 1 headlight) (4)	\$ 4.00
P057	10.154	84-85 <b>kit</b> , W/S washer reservoir mounting	\$ 1.50
P058	10.154	86-88 <b>kit</b> , W/S washer reservoir mounting	\$ 1.50
P059	10.515	84-88 <b>kit</b> , inside door handle bezel mounting (2 screws, 2 plugs) (paint to match)	\$ 3.00
P060	12.212	84-88 rubber <b>bumper</b> , trunk lid (4)	\$ 9.00
P061	8.024	84-88 rubber <b>bumper</b> , hood to cowl (2)	\$ 7.00
P062	15.300	84-88 <b>plug</b> , inside door sill retainer (does one side) (paint to match) (5)	\$ 5.00
P063	10.515	84-88 <b>plug</b> , inside door handle bezel (paint to match) (2)	\$ 2.00
P064	2.760	84-88 <b>clip</b> , "E" style for headlight crank arms (does both lights) (4)	\$ 1.00
P065	2.363	85-88 (2.8) <b>O-ring</b> , distributor (high temperature)	\$ 1.25
P066	9.650	84-88 <b>screw</b> , front radio speaker (does both speakers) (8)	\$ 4.00
P067	9.650	84-88 <b>screw and nut</b> , front radio speakers (does both speakers) (16)	\$ 8.00
P068	10.515	84-88 <b>screw</b> , inside door handle bezel (does both doors) (2)	\$ 1.00
P069	7.800	84-88 <b>screw</b> , license plate mounting (SS) (2)	\$ 1.00
P070	2.596	84-88 <b>socket</b> , backup light	\$ 11.00
P071	11.011	86-88 (P97) <b>kit</b> , quarter turbo scoop window (screws, nuts and washers) (SS) (136)	\$ 10.00
P072	2.480	84-88 <b>socket</b> , headlight	\$ 5.00
P073	9.735	86-88 <b>screw</b> , auxiliary gauge pod bezel above console (4)	\$ 2.00
P074	12.895	84-88 <b>block and bolt</b> , door skin adjustment (does 1 door) (1)	\$ 5.00
P075	7.831	84-88 <b>rivet</b> , energy absorbing strip (10)	\$ 6.50
P076	7.831	84-88 (P37) <b>rivet</b> , rear bumper cover (at bottom of cover) (7)	\$ 4.00
P077	10.219	84-88 <b>screw</b> , sunvisor bracket (6)	\$ 1.50
P078	12.181	84-88 <b>retainer</b> , rear deck grille bottom screen retainers (9)	\$ 2.50
P079	13.090	85-88 <b>retainer</b> , wiring at windshield pillar (1)	\$ 1.00
P080	9.650	84-88 <b>screw</b> , radio mounting (4)	\$ 1.50
P081	2.335	84-88 <b>bolt and washer</b> , battery hold down clamp	\$ 1.25
P082	2.760	84-88 <b>bolt and washer</b> , headlight actuator mounting (does 1 headlight)	\$ 2.50
P083	2.755	84-88 <b>screw</b> , various relay mounting (2)	\$ 0.75
P084	1.055	84-88 <b>repair harness</b> , fan switch	\$ 13.00
P085	12.800	86-88 (P37) <b>retainer</b> , cowl screen (5)	\$ 7.50
P086	12.800	86-88 (P97) <b>retainer</b> , cowl screen (7)	\$ 10.50
P087	10.056	84-88 <b>clip</b> , windshield pillar interior molding (does both sides) (8)	\$ 8.00
P088	12.895	84-88 tee <b>nut</b> , door outer panel mounting (2)	\$ 4.00
P089	12.895	84-88 tee <b>nut</b> , door outer panel mounting, top	\$ 6.00
P090	12.895	84-88 tee <b>nut</b> , door outer panel mounting, lower	\$ 5.00
P091	12.940	84-88 <b>pad</b> , large, body panel mounting (2)	\$ 7.00
P092	12.810	84-88 <b>pad</b> , small, body panel mounting (2)	\$ 5.00
P093	2.575	84-88 <b>screw</b> , side marker light (black oxide on SS) (4)	\$ 3.00
P094	10.806	84-88 <b>clip</b> , "C" shaped, window crank handle (2)	\$ 0.75
P095	11.373	84-88 <b>hog ring</b> , for upholstery (50)	\$ 1.50
P096	10.783	85-87 <b>rivet</b> , cam to door window, 85-88 upper stops to door glass	\$ 2.00
P097	12.118	84-87 <b>clip</b> , grooved body side molding, door and quarter panel (does one side) (6)	\$ 5.00
P098	15.222	84-88 <b>retainer</b> , black, carpet near firewall, trunk carpet (2)	\$ 2.00
P099	8.133	84-88 <b>rivet w/ washer</b> , rocker panel, body moldings (4 of each)	\$ 6.00
P100	3.601	85-88 (2.8) <b>stud and nut</b> , exhaust manifold (12 of each)	\$ 14.00

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	price
P101	8.921	84-88 <b>nut</b> , body side molding clip on front fender, in front of door (2)	\$ 1.50
P102	1.263	84-88 <b>screw</b> , front bumper cover reinforcement (4)	\$ 2.00
P103	10.527	84-88 <b>clip</b> , outside door handle to lift bar rod end	\$ 1.00
P104	12.801	84-88 w/ A/C, <b>retainer</b> , radiator lower seal to A/C condensor (4)	\$ 2.50
P105	10.155	84-88 <b>nut</b> , exterior rearview mirror mounting (does 1 mirror) (2)	\$ 1.50
P106	6.518	84-88 <b>nut</b> , steering column mounting (2)	\$ 2.00
P107	10.685	84 <b>bushing</b> , door glass to track (1)	\$ 4.00
P108	7.831	84-88 <b>nut</b> , front bumper impact bar (8)	\$ 3.00
P109	12.116	86-88 (P37) <b>screw</b> , quarter body side molding just behind door (does both sides) (2)	\$ 1.25
P110	12.118	84-88 <b>clip</b> w/ screw, body side molding, door (2 of each)	\$ 4.00
P111	12.118	84-88 <b>clip</b> w/ rivet, body side molding, quarter panel (2 of each)	\$ 4.50
P112	10.240	84-88 <b>screw</b> , power mirror switch plate (4)	\$ 2.00
P113	9.273	84-88 <b>screw</b> , heater-A/C control panel (2)	\$ 1.00
P114	10.252	84-88 <b>screw</b> , armrest console mounting (4)	\$ 2.00
P115	10.240	84-88 <b>screw</b> , shift console mounting (4)	\$ 2.00
P116	10.240	84-88 <b>screw</b> , radio, heat, and A/C console housing mounting (4)	\$ 2.00
P117	9.753	86-88 <b>screw</b> , auxiliary gauge pod mounting (4)	\$ 2.00
P118	12.934	84-87 <b>rivet</b> , bottom of rocker cover panel (7)	\$ 4.00
P119	12.934	88 <b>rivet</b> w/ washer, bottom of rocker cover panel (7 of each)	\$ 12.00
P120	6.000	84-88 <b>cap</b> , for grease fitting w/ integral retaining ring (4)	\$ 2.00
P121	1.276	86-88 <b>rivet</b> , engine splash shield (5)	\$ 3.00
P122	12.118	84 <b>nut</b> , engine grille to deck lid	\$ 1.50
P123	10.695	84-88 <b>retainer</b> , door weatherstrip (20)	\$ 1.00
P124	10.240	84-88 grommet <b>nut</b> , pad to ECM bracket (console) (2)	\$ 3.00
P125	8.016	84-88 grommet <b>nut</b> , front floor console trim pad (2)	\$ 3.00
P126	8.153	84-88 <b>rivet</b> , front fender inner wheel house (2)	\$ 1.00
P127	7.832	84-88 <b>nut</b> , front emblem	\$ 0.75
P128	12.942	84-88 (P37) <b>nut</b> , quarter window (does 2 sides) (2)	\$ 1.50
P129	10.527	84-88 <b>nut</b> , exterior door handle assembly (does 2 sides) (4)	\$ 3.00
P130	2.760	87-88 <b>kit</b> , headlight motor rebuild, torque pins (does 1 side) (3)	\$ 5.00
P131	2.760	87-88 <b>kit</b> , headlight motor rebuild, torque pins (does 2 sides) (6)	\$ 9.00
P132	2.535	84-88 <b>repair harness</b> , power window motor	\$ 8.00
P133	2.896	84-88 <b>cam</b> , turn signal repair	\$ 14.00
P134	2.895	84-88 <b>switch</b> , turn signal	\$ 55.00
P135	12.934	86-88 <b>nut &amp; rivet</b> , ground effects on front fender (above rocker) (5)	\$ 2.00
P136	12.934	86-88 <b>nut &amp; rivet</b> , ground effects on door (above rocker) (12)	\$ 4.50
P137	12.934	86-88 <b>nut &amp; rivet</b> , ground effects on quarter panel (above rocker) (8)	\$ 3.00
P138	12.934	86-88 <b>nut &amp; rivet</b> , ground effects (above rocker) (does 1 side) (25)	\$ 9.50
P139	2.999	84-88 <b>bulb</b> , A/C control, heater control (2) (see chart)	\$ 2.50
P140	2.999	84-88 <b>bulb</b> , lighter, ashtray, gear selector (1) (see chart)	\$ 2.00
P141	2.999	86-88 <b>bulb</b> , 2.8 w/ auxilliary gauge pod (2) (see chart)	\$ 2.00
P142	2.999	84-88 <b>bulb</b> , courtesy, front luggage, AM radio (2) (see chart)	\$ 2.00
P143	2.999	84-88 <b>bulb</b> , license, markers, instruments, warnings, "PONTIAC" (2) (see chart)	\$ 2.00
P144	2.999	84-88 <b>bulb</b> , rear luggage compartment (1) (see chart)	\$ 2.00
P145	2.999	84-88 <b>bulb</b> , reading/dome (2) (see chart)	\$ 3.00
P146	2.999	84-88 <b>bulb</b> , back-up (2) (see chart)	\$ 2.00
P147	2.999	84-88 <b>bulb</b> , park/directional, tail, stop (2) (see chart)	\$ 2.00
P148	2.999	86-88 <b>bulb</b> , high position brake light (1) (see chart)	\$ 10.00
P149	2.999	84-85 <b>bulb</b> , glove compartment (1) (see chart)	\$ 1.00
P150	2.187	84-86 <b>key</b> , ignition and deck, plain w/o boot	\$ 3.00

# Fiero hardware from Pony Enterprises Inc.

by part #

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	price
P151	2.187	87-88 <b>key</b> , ignition and deck, plain w/o boot	\$ 3.00
P152	10.093	84-88 <b>filler strip</b> , windshield (1) (see P165 for rear window)	\$ 18.00
P153	12.112	84-88 <b>screw</b> , molding at rear of door (1)	\$ 0.75
P154	12.112	84-85 <b>kit</b> , door molding (grooved) (7)	\$ 7.50
P155	8.132	84-87 <b>kit</b> , fender molding (grooved) (4)	\$ 9.00
P156	12.116	84-85 <b>kit</b> , rear quarter molding (grooved) (6)	\$ 6.00
P157	12.116	86-87 <b>kit</b> , rear quarter molding (grooved) (6)	\$ 6.00
P158	12.112	86-87 <b>kit</b> , door molding (grooved) (8)	\$ 8.00
P159	8.132	86-88 <b>kit</b> , fender molding (smooth) (5)	\$ 8.00
P160	12.112	86-88 <b>kit</b> , door molding (smooth) (9)	\$ 9.00
P161	12.112	86-88 <b>kit</b> , rear quarter molding (smooth) (5)	\$ 5.50
P162	8.130	84-88 <b>kit</b> , fender lower aero molding (7)	\$ 8.00
P163	12.934	84-88 <b>kit</b> , door lower aero molding (19)	\$ 20.00
P164	12.934	84-88 <b>kit</b> , quarter lower aero molding (11)	\$ 13.00
P165	11.208	84-88 <b>filler strip</b> , rear window (across bottom of window) (1) (see P152 for windshield)	\$ 9.00
P166	10.783	84-88 <b>gear</b> , power window motor repair (larger gear) (1)	\$ 18.00
P167	10.783	84-88 <b>gear</b> , power window motor repair (smaller gear) (1)	\$ 17.00
P168	2.760	84-88 <b>nut</b> , crank arm to headlight actuator (2)	\$ 1.00
P169	2.760	84-86 <b>kit</b> , headlight motor rebuild, rubber bumpers (does 1 side) (26)	\$ 8.00
P170	2.760	84-86 <b>screw</b> , headlight actuator brush/relay cover (SS) (does 1 actuator) (3)	\$ 1.00
P171	12.249	84-88 <b>screw</b> , deck lid lock cylinder retainer (2)	\$ 1.50
P172	2.341	84-88 <b>switch</b> , battery disconnect (fits any side post battery)	\$ 20.00
P173	8.820	84-88 <b>rubber band</b> , jack handle anti-rattle (black)	\$ 2.00
P174	9.190	84-88 <b>kit</b> , A/C condensor mounting (8)	\$ 16.00
P175	11.377	84-88 <b>rivet</b> , seat back angle adjust handle	\$ 1.00
P176	14.685	84-88 <b>clip</b> , inner door panel (8)	\$ 5.00
P177	8.153	84-88 <b>screw</b> , front wheel house liner (7)	\$ 6.00
P178	8.153	84-88 <b>screw</b> , rear wheel house liner (11)	\$ 9.00
P179	8.153	84-88 <b>screw</b> , wheel house liners (does all 4) (36)	\$ 26.00
P180	3.275	85-88 (2.8) <b>bolt</b> , upper intake manifold plenum (chrome) (12)	\$ 18.00
P181	2.535	84-86 <b>repair harness</b> , headlight motor (single blue wire)	\$ 6.00
P182	2.535	84-86 <b>repair harness</b> , headlight harness (single blue wire)	\$ 8.50
P183	2.535	87-88 <b>repair harness</b> , headlight motor	\$ 9.00
P184	2.535	87-88 <b>repair harness</b> , headlight harness	\$ 8.50
P185	1.240	84-88 <b>clamp</b> , radiator to overflow reservoir hose (2)	\$ 2.50
P186	9.647	84-88 <b>grommet</b> , radio antenna on fender (NOS)	\$ 3.00
P187	2.765	84-88 <b>bumper</b> , headlight door (does 2 doors) (4)	\$ 6.00
P188	2.187	84/ <b>key</b> , deck lid ("H" groove)	\$ 3.00
P189	12.942	84-88 coupe <b>clip</b> , sail panel (2)	\$ 6.00
P190	8.153	84-88 <b>retainer</b> , wheel well (screw rivet) (8)	\$ 5.00
P191	8.153	84-88 <b>nut</b> , front fender well (goes with P177) (7)	\$ 5.00
P192	12.944	84-88 <b>nut</b> , rear fender well (goes with P178) (11)	\$ 7.50
P193	1.272	84-88 <b>kit</b> , front fascia to radiator splash shield (all w/ aero nose) (16)	\$ 9.00
P194	2.760	87-88 <b>kit</b> , headlight motor rebuild w/ 1 gear & 3 pins (does 1 side) (4)	\$ 17.00
P195	2.760	87-88 <b>kit</b> , headlight motor rebuild w/ 2 gears & 6 pins (does 2 sides) (8)	\$ 34.00
P196	10.710	84-88 <b>screw</b> , outer dew wipe (does 2 sides) (SS) (10)	\$ 4.00
P197	10.710	84-88 <b>screw</b> , outer dew wipe w/larger threads for repair (SS) (5)	\$ 3.00
P198	2.760	84-86 <b>kit</b> , headlight motor rebuild (does 1 side) (27)	\$ 20.00
P199	2.760	84-86 <b>kit</b> , headlight motor rebuild (does 2 sides) (54)	\$ 40.00
P200	12.810	84-88 <b>bolt</b> , sunroof weatherstrip track (6)	\$ 9.00

# Fiero hardware from Pony Enterprises Inc.

by part #

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	price
P201	12.934	84-87 <b>kit</b> , rocker panel cover mount (15)	\$ 9.00
P202	12.934	88 <b>kit</b> , rocker panel cover mount (22)	\$ 17.00