

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	Price
------	--------	-------------	-------

0.000 - engine, clutch

P065	2.363	85-88 (2.8) O-ring , distributor (high temperature)	\$ 1.25
P180	3.275	85-88 (2.8) bolt kit , upper intake manifold plenum (chrome) (12)	\$ 18.00
P037	2.535	87-88 repair harness , throttle body injector	\$ 12.00
P038	2.535	88 repair harness , oil pressure switch	\$ 24.00
P039	2.535	84-88 repair harness , MAP sensor	\$ 15.00
P040	2.535	84-88 repair harness , idle air control valve	\$ 18.00
P041	2.535	87-88 repair harness , voltage regulator module	\$ 19.00
P042	2.535	87-88 repair harness , ignition distributor module	\$ 16.00

1.000 - cooling, grille, oil system

P043	2.535	85-86 repair harness , cooling fan temperature switch	\$ 18.00
P084	1.055	84-88 repair harness , fan switch	\$ 13.00
P185	1.240	84-88 clamp , radiator to overflow reservoir hose (2)	\$ 2.50
P102	1.263	84-88 screw , front bumper cover reinforcement (4)	\$ 2.00
P193	1.272	84-88 kit , front fascia to radiator splash shield (all w/ aero nose) (16)	\$ 9.00
P121	1.276	86-88 rivet , engine splash shield (5)	\$ 3.00
P053	1.453	85-86 (2.8) plug , oil drain	\$ 2.50
P054	1.453	84-87 (2.5), 87-88 (2.8), plug , oil drain	\$ 3.00

2.000 - keys, locks

P014	2.187	84-86 key , ignition w/ black molded boot "GM" (50A groove)	\$ 3.00
P015	2.187	84-86 key , deck w/ black molded boot "GM" (51B groove)	\$ 3.00
P016	2.187	84-86 keys , ignition and deck w/ black molded boot "GM"	\$ 6.00
P017	2.187	87-88 key , ignition w/ black molded boot "GM" (54C groove)	\$ 3.00
P018	2.187	87-88 key , deck w/ black molded boot "GM" (55D groove)	\$ 3.00
P019	2.187	87-88 keys , ignition and deck w/ black molded boot "GM"	\$ 6.00
P020	2.187	84-88 key boot , rectangular for ignition key (GM)	\$ 1.00
P021	2.187	84-88 key boot , oval for deck key "GM"	\$ 1.00
P022	2.187	84-88 key boot , 1 rectangular, 1 oval "GM"	\$ 2.00
P150	2.187	84-86 key , ignition and deck, plain w/o boot	\$ 3.00
P151	2.187	87-88 key , ignition and deck, plain w/o boot	\$ 3.00
P188	2.187	84/ key , deck lid ("H" groove)	\$ 3.00
P009	2.188	84-88 repair harness , ignition switch	\$ 15.00
P010	2.188	84-88 lock , ignition, chrome w/ 2 keys and retaining screw	\$ 26.00
P011	2.188	84-87 lock , ignition, black w/ 2 keys and retaining screw	\$ 29.00
P013	10.470	84-88 lock set , door, bright cover-black shutter (2 locks, 2 clips, 2 keys)	n/a
P008	10.485	84-88 actuator , power door lock	n/a
P012	12.248	84-88 (P37) lock , deck lid w/ 2 keys, 2 shafts and a return spring	\$ 28.00
P171	12.249	84-88 screw , deck lid lock cylinder, retainer (2)	\$ 1.50

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	Price
<u>2.000 - light sockets, electrical repair harnesses</u>			
P036	2.535	86-88 repair harness , low freon pressure switch (at A/C compressor)	\$ 14.00
P037	2.535	87-88 repair harness , throttle body injector	\$ 12.00
P038	2.535	88 repair harness , oil pressure switch	\$ 24.00
P039	2.535	84-88 repair harness , MAP sensor	\$ 15.00
P040	2.535	84-88 repair harness , idle air control valve	\$ 18.00
P041	2.535	87-88 repair harness , voltage regulator module	\$ 19.00
P042	2.535	87-88 repair harness , ignition distributor module	\$ 16.00
P009	2.188	84-88 repair harness , ignition switch	\$ 15.00

<u>2.000 - light sockets, electrical repair harnesses (continued)</u>			
P043	2.535	85-86 repair harness , cooling fan temperature switch	\$ 18.00
P084	1.055	84-88 repair harness , fan switch	\$ 13.00
P044	2.535	85-88 repair harness , A/C pressure switch	\$ 15.00
P132	2.535	84-88 repair harness , power window motor	\$ 8.00
P181	2.535	84-86 repair harness , headlight motor (single blue wire)	\$ 6.00
P182	2.535	84-86 repair harness , headlight harness (single blue wire)	\$ 8.50
P183	2.535	87-88 repair harness , headlight motor	\$ 9.00
P184	2.535	87-88 repair harness , headlight harness	\$ 8.50
P072	2.480	84-88 socket , headlight	\$ 5.00
P052	2.575	84-88 socket , side marker light	\$ 11.00
P051	2.596	84-88 socket , park / turn signal light	\$ 11.00
P070	2.596	84-88 socket , backup light	\$ 11.00
P050	2.694	84-88 socket , tail, turn and stop light	\$ 14.00
P049	2.714	84-88 socket , license plate light	\$ 11.00

<u>2.000 - headlight, headlight rebuild kits</u>			
P072	2.480	84-88 socket , headlight	\$ 5.00
P046	2.728	84-88 kit , headlight bezel mounting (8)	\$ 4.00
P002	2.736	84-88 screw , headlight ring (8) (SS) (does both headlights)	\$ 3.00
P045	2.737	84-88 kit , headlight adjustment (does 1 headlight) (2 screws, 2 nuts, 1 spring)	\$ 5.00
P056	2.760	84-88 nut , headlight assembly to body (does 1 headlight) (4)	\$ 4.00
P064	2.760	84-88 clip , "E" style for headlight crank arms (does both lights) (4)	\$ 1.00
P082	2.760	84-88 bolt and washer, headlight actuator mounting (does 1 headlight) (3 of each)	\$ 2.50
P169	2.760	84-86 kit , headlight motor rebuild, rubber bumpers (does 1 side) (26)	\$ 8.00
P198	2.760	84-86 kit, headlight motor rebuild (does 1 side) (27)	\$ 20.00
P199	2.760	84-86 kit, headlight motor rebuild (does 2 sides) (54)	\$ 40.00
P194	2.760	87-88 kit , headlight motor rebuild w/ 1 gear & 3 pins (does 1 side) (4)	\$ 17.00
P195	2.760	87-88 kit , headlight motor rebuild w/ 2 gears & 6 pins (does 2 sides) (8)	\$ 34.00
P130	2.760	87-88 kit , headlight motor rebuild, torque pins (does 1 side) (3)	\$ 5.00
P131	2.760	87-88 kit , headlight motor rebuild, torque pins (does 2 sides) (6)	\$ 9.00
P168	2.760	84-88 nut , crank arm to headlight actuator (2)	\$ 1.00
P170	2.760	84-86 screw , headlight actuator brush/relay cover (SS) (does 1 actuator) (3)	\$ 1.00
P187	2.765	84-88 bumper , headlight door (does 2 doors) (4)	\$ 6.00
P181	2.535	84-86 repair harness , headlight motor (single blue wire)	\$ 6.00
P182	2.535	84-86 repair harness , headlight harness (single blue wire)	\$ 8.50
P183	2.535	87-88 repair harness , headlight motor	\$ 9.00
P184	2.535	87-88 repair harness , headlight harness	\$ 8.50

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	Price
------	--------	-------------	-------

2.000 - chassis wiring, turn signals, battery

P004	2.341	84-88 bolt , battery cable terminal (2)	\$ 5.00
P081	2.335	84-88 bolt and washer, battery hold down clamp	\$ 1.25
P172	2.341	84-88 switch , battery disconnect (fits any side post battery)	\$ 20.00
P065	2.363	85-88 (2.8) O-ring , distributor (high temperature)	\$ 1.25
P093	2.575	84-88 screw , side marker light (black oxide on SS) (4)	\$ 3.00
P047	2.585	84-88 screw , parking light lens (does both lights) (SS) (4)	\$ 3.00
P048	2.585	84-88 screw and nut , parking light lens (does both lights) (8)	\$ 5.00
P083	2.755	84-88 screw , various relay mounting (2)	\$ 0.75
P134	2.895	84-88 switch , turn signal	\$ 55.00
P133	2.896	84-88 cam , turn signal switch repair	\$ 14.00

2.000 - bulbs

P139	2.999	84-88 bulb , A/C control, heater control (2) (see chart)	\$ 2.50
P140	2.999	84-88 bulb , lighter, ashtray, gear selector (1) (see chart)	\$ 2.00
P141	2.999	86-88 bulb , 2.8 w/ auxilliary gauge pod (2) (see chart)	\$ 2.00
P142	2.999	84-88 bulb , courtesy, front luggage, AM radio (2) (see chart)	\$ 2.00
P143	2.999	84-88 bulb , license, markers, instruments, warnings, "PONTIAC" (2) (see chart)	\$ 2.00
P144	2.999	84-88 bulb , rear luggage compartment (1) (see chart)	\$ 2.00
P145	2.999	84-88 bulb , reading/dome (2) (see chart)	\$ 3.00
P146	2.999	84-88 bulb , back-up (2) (see chart)	\$ 2.00
P147	2.999	84-88 bulb , park/directional, tail, stop (2) (see chart)	\$ 2.00
P148	2.999	86-88 bulb , high position brake light (1) (see chart)	\$ 10.00
P149	2.999	84-85 bulb , glove compartment (1) (see chart)	\$ 1.00

3.000 - fuel, exhaust, fuel injection

P100	3.601	85-88 (2.8) stud and nut , exhaust manifold (12 of each)	\$ 14.00
P180	3.275	85-88 (2.8) bolt , upper intake manifold plenum (chrome) (12)	\$ 18.00
P027	12.940	84-88 screw , air intake grille (drivers side quarter panel) (2)	\$ 2.50
P028	12.940	84-88 screw and nut , air intake grille (drivers side quarter panel) (4 of ea)	\$ 4.50
P037	2.535	87-88 repair harness , throttle body injector	\$ 12.00
P039	2.535	84-88 repair harness , MAP sensor	\$ 15.00
P040	2.535	84-88 repair harness , idle air control valve	\$ 18.00

4.000 - transmission, brakes

5.000 - brakes, rear axle, wheels

6.000 - front suspension, steering

P120	6.000	84-88 cap , for grease fitting w/ integral retaining ring (4)	\$ 2.00
P106	6.518	84-88 nut , steering column mounting (2)	\$ 2.00

Fiero hardware from Pony Enterprises, Inc.

by group #

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	Price
------	--------	-------------	-------

7.000 - frame, springs, shocks, bumpers

P069	7.800	84-88 screw , license plate mounting (SS) (2)	\$ 1.00
P075	7.831	84-88 rivet , energy absorbing strip (10)	\$ 10.00
P076	7.831	84-88 (P37) rivet , rear bumper cover (at bottom of cover) (7)	\$ 7.00
P108	7.831	84-88 nut , front bumper impact bar (8)	\$ 3.00
P024	7.832	87-88 (P37) 88 Formula nut , "PONTIAC" on rear panel (3)	\$ 1.50
P127	7.832	84-88 nut , front emblem	\$ 0.75
P023	8.921	86-88 nut , "GT" on rear panel (2)	\$ 1.00

8.000 - front end sheet metal, heater, labels

P125	8.016	84-88 grommet nut , front floor console trim pad (2)	\$ 3.00
P061	8.024	84-88 rubber bumper , hood to cowl (2)	\$ 7.00
P162	8.130	84-88 kit , fender lower aero molding (7)	\$ 8.00
P155	8.132	84-87 kit , fender molding (grooved) (4)	\$ 9.00
P159	8.132	86-88 kit , fender molding (smooth) (5)	\$ 8.00
P099	8.133	84-88 rivet w/ washer , rocker panel, body moldings (4 of each)	\$ 6.00
P126	8.153	84-88 rivet , front fender inner wheel house (2)	\$ 1.50
P177	8.153	84-88 screw , front wheel house liner (7)	\$ 6.00
P191	8.153	84-88 nut , front fender well (goes with P177) (7)	\$ 5.00
P178	8.153	84-88 screw , rear wheel house liner (11)	\$ 9.00
P192	12.944	84-88 nut , rear fender well (goes with P178) (11)	\$ 7.50
P179	8.153	84-88 screw , wheel house liners (does all 4) (36)	\$ 26.00
P190	8.153	84-88 retainer , wheel well (screw rivet) (8)	\$ 5.00
P173	8.820	84-88 rubber band , jack handle anti-rattle (black)	\$ 2.00
P023	8.921	86-88 nut , "GT" on rear panel (2)	\$ 1.00
P101	8.921	84-88 nut , body side molding clip on front fender, in front of door (2)	\$ 1.50

9.000 - radio, air conditioning, instrument cluster

P174	9.190	84-88 kit , A/C condensor mounting (8)	\$ 16.00
P113	9.273	84-88 screw , heater-A/C control panel (2)	\$ 1.00
P044	2.535	85-88 repair harness , A/C pressure switch	\$ 15.00
P186	9.647	84-88 grommet , radio antenna on fender	\$ 3.00
P066	9.650	84-88 screw , front radio speaker (does both speakers) (8)	\$ 4.00
P067	9.650	84-88 screw and nut , front radio speakers (does both speakers) (16)	\$ 8.00
P080	9.650	84-88 screw , radio mounting (4)	\$ 1.50
P034	9.667	84-88 retainer , radio (nylon pin in back of radio)	\$ 2.00
P035	9.667	84-88 nut , front radio speaker (does both speakers) (8)	\$ 4.00
P073	9.735	86-88 screw , auxiliary gauge pod bezel above console (4)	\$ 2.00
P117	9.753	86-88 screw , auxiliary gauge pod mounting (4)	\$ 2.00
P116	10.240	84-88 screw , radio, heat, and A/C console housing mounting (4)	\$ 2.00

Fiero hardware from Pony Enterprises, Inc.

by group #

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	Price
------	--------	-------------	-------

10.000 - console, regulators, windshield, wipers, washers

P087	10.056	84-88 clip , windshield pillar interior molding (does both sides) (8)	\$ 8.00
P152	10.093	84-88 filler strip , windshield (1) (see P165 for rear window)	\$ 18.00
P057	10.154	84-85 kit , W/S washer reservoir mounting	\$ 1.50
P058	10.154	86-88 kit , W/S washer reservoir mounting	\$ 1.50
P105	10.155	84-88 nut , exterior rearview mirror mounting (does 1 mirror) (2)	\$ 1.50
P077	10.219	84-88 screw , sunvisor bracket (6)	\$ 1.50
P112	10.240	84-88 screw , power mirror switch plate (4)	\$ 2.00
P115	10.240	84-88 screw , shift console mounting (4)	\$ 2.00
P116	10.240	84-88 screw , radio, heat, and A/C console housing mounting (4)	\$ 2.00
P124	10.240	84-88 grommet nut , pad to ECM bracket (console) (2)	\$ 3.00
P114	10.252	84-88 screw , armrest console mounting (4)	\$ 2.00

10.000 - doors

P032	10.466	84-88 pins and bushings , door hinge (does 1 door)	\$ 6.00
P033	10.466	84-88 pins and bushings , door hinge (does both doors)	\$ 12.00
P013	10.470	84-88 lock set , door, bright cover-black shutter (locks, 2 clips, 2 keys)	n/a
P008	10.485	84-88 actuator , power door lock	n/a
P176	14.685	84-88 clip , inner door panel (8)	\$ 5.00
P003	14.686	84-88 screw , armrest (does both doors) (6)	\$ 3.00
P026	14.686	84 nut , arm rest to hanger plate (2)	\$ 3.00
P059	10.515	84-88 kit , inside door handle bezel mounting (2 screws, 2 plugs) (paint to match)	\$ 3.00
P063	10.515	84-88 plug , inside door handle bezel (paint to match) (2)	\$ 2.00
P068	10.515	84-88 screw , inside door handle bezel (does both doors) (2)	\$ 1.00
P007	12.895	84-88 screw , nylon encapsulated torx head, door skin to frame (does one door) (7)	\$ 10.00
P088	12.895	84-88 tee nut , door outer panel mounting (2)	\$ 4.00
P089	12.895	84-88 tee nut , door outer panel mounting, top	\$ 6.00
P090	12.895	84-88 tee nut , door outer panel mounting, lower	\$ 5.00
P031	10.527	84-88 clip , outside door handle rod to lock	\$ 1.00
P103	10.527	84-88 clip , outside door handle to lift bar rod end	\$ 1.00
P129	10.527	84-88 nut , exterior door handle assembly (does 2 sides) (4)	\$ 3.00
P123	10.695	84-88 retainer , door weatherstrip (20)	\$ 1.00
P196	10.710	84-88 screw, outer dew wipe (does 2 sides) (SS) (10)	\$ 4.00
P197	10.710	84-88 screw, outer dew wipe w/larger threads for repair (SS) (5)	\$ 3.00

10.000 - windows

P107	10.685	84 bushing , door glass to track (1)	\$ 4.00
P025	10.716	84-88 stop , door window	\$ 4.00
P030	10.783	84-88 actuator , power window	\$115.00
P096	10.783	85-87 rivet , cam to door window, 85-88 upper stops to door glass	\$ 2.00
P166	10.783	84-88 gear , power window motor repair (larger gear) (1)	\$ 18.00
P167	10.783	84-88 gear , power window motor repair (smaller gear) (1)	\$ 17.00
P094	10.806	84-88 clip , "C" shaped, window crank handle (2)	\$ 0.75

Fiero hardware from Pony Enterprises, Inc.

by group #

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	Price
------	--------	-------------	-------

11.000 - rear glass, seat parts, adjuster

P071	11.011	86-88 (P97) kit , quarter turbo scoop window (screws, nuts and washers) (SS) (136)	\$ 10.00
P165	11.208	84-88 filler strip , rear window (across bottom of window) (1) (see P152 for windshield)	\$ 9.00
P095	11.373	84-88 hog ring , for upholstery (50)	\$ 1.50
P175	11.377	84-88 rivet , seat back angle adjust handle	\$ 1.00
P055	11.561	84-88 nut , seat track to floor (does 1 seat) (4)	\$ 4.00

12.000 - body moldings, molding mounting kits

P153	12.112	84-88 screw , molding at rear of door (1)	\$ 0.75
P154	12.112	84-85 kit , door molding (grooved) (7)	\$ 11.25
P155	8.132	84-87 kit , fender molding (grooved) (4)	\$ 9.00
P156	12.116	84-85 kit , rear quarter molding (grooved) (6)	\$ 10.25
P157	12.116	86-87 kit , rear quarter molding (grooved) (6)	\$ 10.25
P158	12.112	86-87 kit , door molding (grooved) (8)	\$ 14.75
P159	8.132	86-88 kit , fender molding (smooth) (5)	\$ 8.00
P160	12.112	86-88 kit , door molding (smooth) (9)	\$ 15.50
P161	12.112	86-88 kit , rear quarter molding (smooth) (5)	\$ 9.75
P109	12.116	86-88 (P37) screw , quarter body side molding just behind door (does both sides) (2)	\$ 1.25
P162	8.130	84-88 kit , fender lower aero molding (7)	\$ 8.00
P163	12.934	84-88 kit , door lower aero molding (19)	\$ 20.00
P164	12.934	84-88 kit , quarter lower aero molding (11)	\$ 13.00

12.000 - body, sheet metal

P001	12.118	84 fastener , outer door skin to reinforcement at belt (6) (does one door)	\$ 6.00
P005	12.118	84-88 rivet , drive type, body side molding (2)	\$ 2.00
P006	12.118	84-88 rivet , push in type, body side molding (3)	\$ 2.00
P097	12.118	84-87 clip , grooved body side molding, door and quarter panel (does one side) (6)	\$ 5.00
P110	12.118	84-88 clip w/ screw, body side molding, door (2 of each)	\$ 4.00
P111	12.118	84-88 clip w/ rivet, body side molding, quarter panel (2 of each)	\$ 4.50
P118	12.934	84-87 rivet , bottom of rocker cover panel (7)	\$ 7.00
P119	12.934	88 rivet w/ washer, bottom of rocker cover panel (7 of each)	\$ 12.00
P135	12.934	86-88 nut & rivet , ground effects on front fender (above rocker) (5)	\$ 2.00
P136	12.934	86-88 nut & rivet , ground effects on door (above rocker) (12)	\$ 4.50
P137	12.934	86-88 nut & rivet , ground effects on quarter panel (above rocker) (8)	\$ 3.00
P138	12.934	86-88 nut & rivet , ground effects (above rocker) (does 1 side) (25)	\$ 9.50
P122	12.118	84 nut , engine grille to deck lid	\$ 1.50
P078	12.181	84-88 retainer , rear deck grille bottom screen retainers (9)	\$ 2.50
P060	12.212	84-88 rubber bumper , trunk lid (4)	\$ 9.00
P012	12.248	84-88 (P37) lock , deck lid w/ 2 keys, 2 shafts and a return spring	\$ 28.00
P171	12.249	84-88 screw , deck lid lock cylinder retainer (2)	\$ 1.50
P029	12.800	84-88 retainer , cowl vent panel (2)	\$ 4.00
P085	12.800	86-88 (P37) retainer , cowl screen (5)	\$ 7.50
P086	12.800	86-88 (P97) retainer , cowl screen (7)	\$ 10.50
P104	12.801	84-88 w/ A/C, retainer , radiator lower seal to A/C condensor (4)	\$ 2.50
P092	12.810	84-88 pad , small, body panel mounting (2)	\$ 5.00
P091	12.940	84-88 pad , large, body panel mounting (2)	\$ 7.00
P200	12.810	84-88 bolt, sunroof weatherstrip track (6)	\$ 9.00
P007	12.895	84-88 screw , nylon encapsulated torx head, door skin to frame (does one door) (7)	\$ 10.00
P074	12.895	84-88 block and bolt , door skin adjustment (does 1 door) (1)	\$ 5.00

Fiero hardware from Pony Enterprises, Inc.

by group #

Prices shown are suggested retail prices. - Dealer discount to be applied.

Kit#	Group#	Description	Price
<i>12.000 - body, sheet metal</i>			
P088	12.895	84-88 tee nut , door outer panel mounting (2)	\$ 4.00
P089	12.895	84-88 tee nut , door outer panel mounting, top	\$ 6.00
P090	12.895	84-88 tee nut , door outer panel mounting, lower	\$ 5.00
P201	12.934	84-87 kit, rocker panel cover mount (15)	\$ 9.00
P202	12.934	88 kit, rocker panel cover mount (22)	\$ 17.00
P027	12.940	84-88 screw , air intake grille (drivers side quarter panel) (2)	\$ 2.50
P028	12.940	84-88 screw and nut , air intake grille (drivers side quarter panel) (4 of ea)	\$ 4.50
P128	12.942	84-88 (P37) nut , quarter window (does 2 sides) (2)	\$ 1.50
P189	12.942	84-88 (P37) clip , sail panel (2)	\$ 6.00
P190	12.944	84-88 retainer , wheel well (screw rivet) (8)	\$ 5.00
<i>13.000 - body wiring</i>			
P079	13.090	85-88 retainer , wiring at windshield pillar (1)	\$ 1.00
<i>14.000 - interior trim, seat belts</i>			
P176	14.685	84-88 clip , inner door panel (8)	\$ 5.00
P003	14.686	84-88 screw , armrest (does both doors) (6)	\$ 3.00
P026	14.686	84 nut , arm rest to hanger plate (2)	\$ 3.00
<i>15.000 - rear, seat trim, carpet</i>			
P098	15.222	84-88 retainer , black, carpet near firewall, trunk carpet (2)	\$ 2.00
P062	15.300	84-88 plug , inside door sill retainer (does one side) (paint to match) (5)	\$ 5.00