

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
CHASSIS 1000-1999: <u>wheels, hubs, drums</u>			
160	1462	65-67, 78-83 (from 5/1/78) wing nut , spare tire	\$5.00
161	1462	68-78 (to 5/1/78) wing nut , spare tire	\$5.00
CHASSIS 2000-2999: <u>brakes, lines, hoses, emergency brake</u>			
108	2000	65-93 cover , drum brake adjusting hole (4)	\$3.00
648	2078	65-74 clip , brake hose retaining (3)	\$3.00
1188	2265	79-93 screw , fuel & brake lines (also see group# 9317) (6)	\$6.00
1207	2471	74-04 bushing , clutch pedal pivot shaft (2)	\$3.00
1021	2853	67-86 retaining clip , emergency brake cable (3)	\$3.00
CHASSIS 3000-3999: <u>front axles, suspension, steering</u>			
788	3000	65/ cap , grease fitting self-retaining (4)	\$3.00
875	3530	79-86 screw , steering column cover (4)	\$1.50
876	3530	87-89 screw , steering column cover (3)	\$1.25
877	3530	90-93 screw , steering column cover (2)	\$1.00
CHASSIS 4000-4999: <u>rear axle, drive shaft</u>			
1232	4033	79/ bolt , 7.5/8.8 differential cover (exc 99-04 Cobra) zinc plated (10)	\$7.00
1079	4141	65-78 locknut & copper washer , differential carrier housing (10 of each)	\$15.00
1080	4141	65-78 copper washer , differential housing (10)	\$6.00
1086	4215	65/ nut , differential pinion	\$5.00
CHASSIS 5000-5999: <u>frame, springs, exhaust</u>			
CHASSIS 6000-6999: <u>engine, mounts, oil system</u>			
205	6730	65-90 (8-27-90) plug , engine oil pan drain (w/ gasket) (1 of each)	\$2.50
1233	6730	65-90 (8-27-90) gasket , engine oil pan drain plug (2)	\$1.00
1234	6730	65-90 (8-27-90) plug , magnetic engine oil drain	\$8.50
1239	6730	65-90 (8-27-90) plug , single oversize engine oil drain	\$5.00
1240	6730	65-90 (8-27-90) plug , double oversize engine oil drain	\$6.00
1241	6730	65-90 (8-27-90) plug , triple oversize engine oil drain	\$6.00
1235	6730	90 (8-27-90) - 10 plug , engine oil drain	\$10.00
1238	6730	90 (8-27-90) - 10 plug , magnetic engine oil drain	\$11.00
1242	6730	90 (8-27-90) - 10 plug , single oversize engine oil drain	\$8.00
1236	6730	11/ plug , engine oil drain	\$4.00
1237	6730	11/ plug , magnetic engine oil drain	\$10.00
1243	6730	11/ plug , single oversize engine oil drain	\$8.00
1059	6256	79-85 high perf 302 dowel , cam gear to cam shaft (w/ 1 piece fuel pump eccentric)	\$5.00
1166	6392	65-95 w/manual trans bolt , bell housing to engine (12)	\$14.00
1164	6582	93 Cobra, 94-95 5.0L, bolts , valve cover (12)	\$18.00
216	14305	65-93 wire cover (loom) , oil pressure sending unit	\$2.00
782	9278	65-93 repair harness , oil pressure sending unit (also see grps 9278, 14000)	\$5.00
783	9278	65-93 repair harness , oil pressure sending unit (w/ cover for wire) (see 9278, 14000)	\$6.50

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
------	--------	-------------	-----

CHASSIS 7000-7999: transmission, clutch, shifter

402	7087	65-83 automatic transmission hose , vacuum modulator	\$2.00
614	7133	65-93 bushing , automatic transmission shifter (2)	\$2.50
1206	7277	79-93 kit , lower shift boot mounting (8)	\$6.00
1275	7277	87-93 retainer , upper shift boot (4)	\$3.00
980	7330	83-93 grommet , throttle valve pressure rod	\$3.50
1306	7513	83-04 screw , clutch fork cover	\$6.00
1208	7553	79-04 retainer , clutch cable (at bell housing)	\$1.00

CHASSIS 8000-8999: cooling system, radiator, water pump, fan, shroud, grille

1173	8080	90-93 repair harness , low coolant sensor (at coolant reservoir)	\$16.00
1174	8080	87-89 repair harness , low coolant sensor (at coolant reservoir)	\$14.00
924	8146	68-78 kit , cooling fan shroud mounting (8)	\$9.00
1048	8146	79-85 5.0 liter kit , cooling fan shroud mounting (6)	\$11.00
1049	8146	86-93 5.0 liter kit , cooling fan shroud mounting (10)	\$16.00
724	8190	79-93 rivet , grille (bumper cover) (various years & models use 11 to 17 of these) (17)	\$16.00
1194	8200	03-04 Mach 1 kit , grille delete (6)	\$6.00
1148	8223	85-93 nut , "FORD" oval emblem on front bumper cover (2)	\$2.00
1195	8224	94-98 all, 99-04 Cobra, 03-04 Mach 1, screws , running horse emblem grille bracket (2)	\$4.00
1088	8284	79-93 kit , fiberglass headlamp reinforcement panel mounting (behind grille) (8)	\$16.00
1107	8621	94-01 repair harness , radiator cooling fan motor	n/a
1270	8349	94-04 kit , radiator air deflector (4)	\$3.75
1090	8390	79-93 kit , radiator air dam deflector mounting (8)	\$6.00
1171	8616	79-93 5.0L bolt , fan clutch to water pump (4)	\$13.00

CHASSIS 9000-9999: fuel system, carburetor, air cleaner, choke

782	9278	65-98 repair harness , oil pressure sending unit (also see grps 6000, 14000)	\$5.00
783	9278	65-93 repair harness , oil pressure sending unit (w/ cover for wire) (see 6000, 14000)	\$6.50
1181	9278	99/ repair harness , oil pressure switch (sending unit) (also 6000, 14000)	\$19.00
1196	9279	81-86 w/CFI, 87-97 all retaining clip , 1/4" fuel supply line	\$2.00
1197	9291	81-86 w/CFI, 87-97 all retaining clip , 5/16" fuel supply line	\$2.00
1149	9291	86-93 "O" ring , fuel line (4)	\$5.00
1188	9317	79-93 screw , fuel & brake lines (also see group# 2265) (6)	\$6.00
1187	9434	86-95 5.0L exc. Cobra screw , nameplate to upper intake (4)	\$5.00
1266	9350	15/ 2.3 liter repair harness , fuel injector & engine mounted fuel pump	\$24.00
897	9472	84-86 repair harness , O2 sensor	\$15.00
664	9510	65-85 nut , carburetor hold down (4)	\$1.50
1020	9686	86-93 stud & nut , factory air box to inner fender (2 of each)	\$16.00
1074	9731	79-04 repair harness , speed sensor wiring harness (at transmission)	\$8.00

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
------	--------	-------------	-----

CHASSIS 10000-10999: alternator, battery, instrument cluster

266	10316	65-86 screw , starter solenoid & voltage regulator (also see group 11450) (4)	\$1.50
1057	10316	65-86 repair harness voltage regulator wiring harness	\$9.00
1142	10316	75-85 repair harness , external voltage regulator	\$10.00
642	10346	65-85 repair harness , alternator (40-60 amp w/ connections on back & external reg)	\$6.00
654	10346	86-93 repair harness , alternator (w/ internal regulator)	\$15.00
1157	10346	87-93 repair harness , alternator (75 amp, larger connector)	\$19.00
656	10655	65/ switch , battery (master cut off)	\$8.50
855	10655	65/ switch , battery (master cut off, w/ fused bypass for accessories)	\$10.00
1099	10732	79-85 kit , battery tray mounting (6)	\$8.00
1097	10732	86-93 kit , battery tray mounting (4)	\$5.00
1100	10756	79-85 bolt and nut, battery hold down	\$1.50
1098	10756	86-93 bolt and nut, battery hold down	\$2.00
975	13765	69-93 all, 94-98 (the larger ones) socket , instrument light bulb (2)	\$7.00

CHASSIS 11000-11999: starter, lighting switches

266	11450	65-86 screw , starter solenoid & voltage regulator (also see group 10316) (4)	\$1.50
1183	11450	87-93 screw , starter solenoid (2)	\$2.00
1189	11572	79-93 screw , ignition switch (2)	\$5.00
921	11654	87-93 repair harness , headlight switch (w/o fog lights) (1)	\$13.00
922	11654	87-93 repair harness , headlight switch (w fog lights) (2)	\$21.00
1120	11654	94-04 repair harness , headlight switch	\$22.00

CHASSIS 12000-12999: coil, distributor, spark plugs

1143	12029	77-85 repair harness , coil to ignition harness	\$9.00
1186	12029	99-04 repair harness , ignition coil	\$18.00
1144	12199	83-85 repair harness , ignition module	\$16.00
896	12199	86-93 repair harness , TFI module	\$25.00
1141	12650	83-93 repair harness , EEC IV test plug (plugs into connector under dash)	\$17.00
1159	12648	86-95 5.0L repair harness , coolant temperature sensor	\$16.00
1158	12697	86-93 5.0L repair harness , air charge temperature sensor	\$18.00

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
------	--------	-------------	-----

CHASSIS 13000-13299: headlights, parking lights

641	13007	65-78 socket , headlight	\$6.00
644	13007	85-04 socket , headlight	\$11.00
1045	13007	87-93 nut , headlight, park and marker light assembly mounting (does 2 sides) (14)	\$12.00
972	13008	94-98 adjuster , headlight horizontal (1)	n/a
982	13008	79-86 (exc. SVO) kit , headlight adjust (does 1 light) (6)	\$10.00
934	13008	94-98 nut , headlight pivot and horizontal adjuster (2)	\$3.00
1258	13008	94-98 nut , headlight vertical adjuster (2)	\$3.00
935	13008	94-98 adjuster , headlight pivot (1)	n/a
1258	13008	94-98 nut , headlight vertical adjuster (2)	\$4.00
937	13008	94-98 adjuster , headlight vertical (1)	\$7.00
933	13032	94-98 clip , retains vertical headlight adjuster to car (does 1 side) (1)	\$2.50
670	13015	70-78 screw , headlight ring (SS) (6)	\$2.00
671	13015	79-86 (except SVO) screw , headlight ring (SS) (16)	\$5.00
672	13015	84-86 SVO screw , headlight ring (SS) (8)	\$2.50
869	13015	79-82 screw , headlight door (black) (also fits 79-86 Capri) (6)	\$2.50
643	13024	65-78 repair harness , headlight dimmer switch	\$7.00
710	13064	74-78 screw , headlight door (SS) (4)	\$1.00
711	13064	79-82 (except SVO) screw , headlight door (also fits 79-86 Capri) (SS) (6)	\$2.00
1106	13147	87-93 clip , headlight adjuster to lens retaining	\$5.00
1046	13200	94-98 nut , parking light mounting (does 2 sides) (2)	\$2.00
1128	13201	87-89 light socket , park/turn signal	\$19.00
1135	13201	90-93 light socket , park/turn signal	\$19.00
1130	13201	94-98 light socket , park/turn signal	\$17.00
1132	13201	94-98, 01-04 repair harness , park/turn signal	\$21.00
1133	13201	99-00 light socket , side marker/turn signal	\$18.00
1134	13201	99-00 repair harness , side marker/turn signal	\$21.00
1131	13201	01-04 light socket , park/turn signal	\$18.00
1127	13201	05/ light socket , park/turn signal	\$9.00
1129	13201	05/ repair harness , park/turn signal	\$16.00
1193	13341	87-93 repair harness , multifunction switch (larger one)	\$19.00

CHASSIS 13300-13399: turn signals

1128	13201	87-89 light socket , park/turn signal	\$17.00
1130	13201	94-98 light socket , park/turn signal	\$11.00
1132	13201	94-98, 01-04 repair harness , park/turn signal	\$21.00
1133	13201	99-00 light socket , side marker/turn signal	\$16.00
1134	13201	99-00 repair harness , side marker/turn signal	\$21.00
1131	13201	01-04 light socket , park/turn signal	\$11.00
1127	13201	05/ light socket , park/turn signal	\$9.00
1129	13201	05/ repair harness , park/turn signal	\$16.00
651	13341	82-86 repair harness , turn signal switch connector (not for flasher)	\$14.00
779	13341	92/ repair harness , multi-function switch	\$16.00
954	13341	94-04 repair harness , multi-function switch (rectangular connector) (1)	\$15.00
1192	13341	87-93 repair harness , multifunction switch (smaller one)	\$13.00

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
CHASSIS 13400-13999: <i>rear lighting, courtesy - dome - instrument lighting</i>			
1101	13200	79-86 kit , turn signal/park light mounting (4)	\$6.00
860	13404	83-93 nut , taillight housing (does 2 sides) (12)	\$12.00
900	13404	79-82 nut , taillight housing (does 2 sides) (12)	\$12.00
1139	13404	79-82 light socket , taillight	\$13.00
928	13450	79-82 retainer , taillight lens (does 1 side) (4)	\$4.00
929	13450	83-86 all, 87-93 GT & Cobra, retainer , taillight lens (does 1 side) (5)	\$5.00
930	13450	87-93 exc. GT & Cobra, retainer , taillight lens (does 1 side) (6)	\$6.00
1050	13450	79-82 retainer & sealer , taillight lens (does 2 sides) (8 clips)	\$18.00
1051	13450	83-86 all, 87-93 GT & Cobra, retainer & sealer , taillight lens (does 2 sides) (10 clips)	\$20.00
1052	13450	87-93 exc. GT & Cobra, retainer & sealer , taillight lens (does 2 sides) (12 clips)	\$22.00
946	13506	79-04 retainer , wiring harness (tape in type, multiple locations) (5)	\$5.00
1103	13550	79-93 screw , license plate light mounting (black) (4)	\$2.00
1140	13550	83-93 light socket , rear license plate light	\$8.00
1175	13550	94-09 kit , license plate light mounting (4)	\$4.00
975	13765	69-93 all, 94-98 (the larger ones) socket , instrument light bulb (2) (see grp# 10000)	\$7.00

CHASSIS 13466: <i>bulbs</i>			
800	13466	65/ bulb , (see chart for application) (type 1) (2)	\$3.00
801	13466	65/ bulb , (see chart for application) (type 8) (2)	\$2.50
802	13466	65/ bulb , (see chart for application) (type 7) (2)	\$2.50
803	13466	65/ bulb , (see chart for application) (type 1) (2)	\$3.00
804	13466	65/ bulb , (see chart for application) (type 5) (2)	\$2.75
805	13466	65/ bulb , (see chart for application) (type 5) (2)	\$3.00
806	13466	65/ bulb , (see chart for application) (type 5) (2)	\$4.00
807	13466	65/ bulb , (see chart for application) (type 9) (2)	\$5.00
808	13466	65/ bulb , (see chart for application) (type 12) (2)	\$3.00
809	13466	65/ bulb , (see chart for application) (type 12) (2)	\$2.50
810	13466	65/ bulb , (see chart for application) (type 12) (2)	\$2.50
811	13466	65/ bulb , (see chart for application) (type 13) (2)	\$6.00
812	13466	65/ bulb , (see chart for application) (type 7) (2)	\$6.00
813	13466	65/ bulb , (see chart for application) (type 21) (2)	\$4.50
814	13466	65/ bulb , (see chart for application) (type 21) (2)	\$5.00
815	13466	65/ bulb , (see chart for application) (type 5) (2)	\$5.00
816	13466	65/ bulb , (see chart for application) (type 15) (1)	\$12.00
817	13466	65/ bulb , (see chart for application) (type 16) (1)	\$12.00
818	13466	65/ bulb , (see chart for application) (type 11) (1)	\$3.00
819	13466	65/ bulb , (see chart for application) (type 11) (2)	\$3.00
820	13466	65/ bulb , (see chart for application) (type 11) (2)	\$4.00
821	13466	65/ bulb , (see chart for application) (type 11) (2)	\$4.00
822	13466	65/ bulb , (see chart for application) (type 9) (2)	\$3.50
823	13466	65/ bulb , (see chart for application) (type 10) (2)	\$3.25
824	13466	65/ bulb , (see chart for application) (type 3) (2)	\$4.00
825	13466	65/ bulb , (see chart for application) (type 2) (2)	\$2.50
826	13466	65/ bulb , (see chart for application) (type 4) (2)	\$3.00
827	13466	65/ bulb , (see chart for application) (type 6) (1)	\$4.50
828	13466	65/ bulb , (see chart for application) (type 8) (2)	\$3.50
829	13466	65/ bulb , (see chart for application) (type 13) (2)	\$3.50

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
CHASSIS 13466: bulbs (continued)			
830	13466	65/ bulb, (see chart for application) (type 13) (2)	\$3.50
831	13466	65/ bulb, (see chart for application) (type 13) (2)	\$3.00
832	13466	65/ bulb, (see chart for application) (type 13) (2)	\$3.50
833	13466	65/ bulb, (see chart for application) (type 7) (2)	\$3.00
834	13466	65/ bulb, (see chart for application) (type 14) (1)	\$3.50
835	13466	65/ bulb, (see chart for application) (type 17)	n/a
836	13466	65/ bulb, (see chart for application) (type 18) (1)	\$8.00
837	13466	65/ bulb, (see chart for application) (type 19) (1)	\$12.00
838	13466	65/ bulb, (see chart for application) (type 2) (1)	\$2.50
839	13466	65/ bulb, (see chart for application) (type 4) (2)	\$4.00
840	13466	65/ bulb, (see chart for application) (type 4) (2)	\$6.00
841	13466	65/ bulb, (see chart for application) (type 6) (1)	\$6.00
842	13466	65/ bulb, (see chart for application) (type 12) (2)	\$3.50
843	13466	65/ bulb, (see chart for application) (type 20) (2)	\$6.00
844	13466	65/ bulb, (see chart for application) (type 20) (1)	\$4.00
845	13466	65/ bulb, (see chart for application) (type 20) (1)	\$5.00
846	13466	65/ bulb, (see chart for application) (type 4) (1)	\$5.00
847	13466	65/ bulb, (see chart for application) (type 14) (1)	\$4.00
848	13466	65/ bulb, (see chart for application) (type 14) (1)	\$5.00
849	13466	65/ bulb, (see chart for application) (type 17)	n/a
850	13466	65/ bulb, (see chart for application) (type 11) (1)	\$5.50
851	13466	65/ bulb, (see chart for application) (type 5) (2)	\$6.00
852	13466	65/ bulb, (see chart for application) (type 14) (1)	\$3.50
853	13466	65/ bulb, (see chart for application) (type 3) (2)	\$4.00
1172	13466	94-04 bulb, (sunvisor vanity) (2)	\$8.00

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
CHASSIS 14000-14999: <u>wiring, harness retainers, repair harnesses</u>			
1173	8080	90-93 repair harness , low coolant sensor (at coolant reservoir)	\$16.00
1174	8080	87-89 repair harness , low coolant sensor (at coolant reservoir)	\$14.00
1107	8621	94-01 repair harness , radiator cooling fan motor	n/a
782	9278	65-93 repair harness , oil pressure sending unit (also see grps 6000, 9278)	\$5.00
783	9278	65-93 repair harness , oil pressure sending unit (w/ cover for wire) (see 6000, 9278)	\$6.50
1181	9278	99/ repair harness , oil pressure switch (sending unit)	\$19.00
1266	9350	15/ 2.3 liter repair harness , fuel injector & engine mounted fuel pump	\$24.00
897	9472	84-86 repair harness , O2 sensor	\$15.00
1074	9731	79-04 repair harness , speed sensor wiring harness (at transmission)	\$8.00
1057	10316	65-86 repair harness , voltage regulator wiring harness	\$9.00
1142	10316	75-85 repair harness , external voltage regulator	\$10.00
642	10346	65-85 repair harness , alternator (40-60 amp w/ connections on back & external reg)	\$6.00
654	10346	86-93 repair harness , alternator (w/ internal regulator)	\$15.00
1157	10346	87-93 repair harness , alternator (75 amp, larger connector)	\$19.00
921	11654	87-93 repair harness , headlight switch (w/o fog lights)	\$13.00
922	11654	87-93 repair harness , headlight switch (w fog lights) (2)	\$21.00
1120	11654	94-04 repair harness , headlight switch	\$22.00
1143	12029	77-85 repair harness , coil to ignition harness	\$9.00
1186	12029	99-04 repair harness , ignition coil	\$18.00
896	12199	86-93 repair harness , TFI module	\$25.00
1144	12199	83-85 repair harness , ignition module	\$16.00
1159	12648	86-95 5.0L repair harness , coolant temperature sensor	\$16.00
1141	12650	83-93 repair harness , EEC IV test plug (plugs into connector under dash)	\$17.00
1158	12697	86-93 5.0L repair harness , air charge temperature sensor	\$18.00
643	13024	65-78 repair harness , headlight dimmer switch	\$7.00
1129	13201	05/ repair harness , park/turn signal	\$16.00
1132	13201	94-98, 01-04 repair harness , park/turn signal	\$21.00
1134	13201	99-00 repair harness , side marker/turn signal	\$21.00
651	13341	82-86 repair harness , turn signal switch connector (not for flasher)	\$14.00
1192	13341	87-93 repair harness , multi-function switch (smaller one)	\$13.00
1193	13341	87-93 repair harness , multi-function switch (larger one)	\$19.00
779	13341	92/ repair harness , multi-function switch	\$16.00
954	13341	94-04 repair harness , multi-function switch (rectangular connector)	\$15.00
216	14305	65-93 wire cover (loom) , oil pressure sending unit	\$4.00
1029	14405	69, 71-73, 79-04 light socket , side marker light	\$9.00
1094	14527	79-86 screw , power window and power door lock switch covers (does 2 sides) (4)	\$2.50
945	14570	94-04 retainer , window regulator switch housing (does 2 sides) (2)	\$4.00
1259	15490	01-14 repair harness , backup light switch	\$16.00
652	17664	69-93 repair harness , windshield washer pump connector	\$9.00
780	19986	86/ repair harness , heater-A/C fan speed switch	\$11.00
1180	21842	99-04 repair harness , door lock actuator	\$14.00
CHASSIS 15000-15999: <u>lamp assemblies, clock, cigar lighter</u>			
1204	15200	94-04 GT, 94-01 Cobra, 03-04 Mach 1 socket , foglight	\$22.00
925	15200	03-04 Cobra socket , fog light lamp (1)	\$10.00
882	15201	79-86 screw , side marker (2)	\$1.00
1259	15490	01-14 repair harness , backup light switch	\$16.00

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
CHASSIS 16000-16999: <i>front fender, aprons, shields, hood, fender bolts</i>			
673	16005	74-78 bolt , fender (black) (8)	\$5.00
674	16005	74-78 bolt , fender (yellow dichromate) (8)	\$5.00
675	16005	74-78 bolt , fender (cadmium) (8)	\$8.00
677	16005	79-85 bolt , fender (7/16" hex head) (yellow dichromate) (6)	\$4.00
678	16005	79-85 bolt , fender (7/16" hex head) (cadmium) (6)	\$6.00
1145	16005	74-78 nut , for fender bolts (8)	\$6.50
1146	16005	79-85 nut , for fender bolts (6)	\$5.00
1147	16005	86-93 nut , for fender bolts (6)	\$7.00
679	16005	86-93 bolt , fender (8mm hex head) (yellow zinc) (6)	\$7.50
1169	16005	86-93 bolt , rear of fender to body (at top and bottom) (4)	\$7.00
1170	16005	79-85 bolt , rear of fender to body (at top and bottom) (4)	\$6.00
1293	16023	79-93 kit , fender support brace (8)	\$6.50
887	16102	79-93 screw , front inner fender well (w/ nuts) (16 screws, 6 nuts)	\$7.80
1274	16102	79-93 retainer , fender liner/splash shield (8)	\$8.00
944	16102	94-04 u-nut , fender apron (8) (does 2 sides)	\$9.00
1161	16102	05/ retainer , front wheel well (5)	\$7.00
1265	16102	15/ retainer , fender well liner (reusable) (4)	\$5.00
1073	16162	91-93 nut , fender and quarter panel body side trim (see grp# 29038) (4)	\$8.00
1078	16162	91-93 nut , fender and quarter panel body side trim (see grp 29038) (does whole car) (14)	\$28.00
1284	16239	15/ retainer , fender side seal (not available from Ford) (8)	\$6.00
1285	16664	79-82 studs & nuts , hood scoop (12)	\$15.00
974	16738	83-93 retainer , hood insulation (14)	\$7.00
987	16738	94-04 retainer , hood insulation (14)	\$17.50
1110	16738	05-14 retainer , hood insulation (1)	\$2.00
1111	16738	05-14 retainer , hood insulation (does entire hood) (13)	\$15.00
1287	16738	15/ retainer , hood insulation (15)	\$12.00
784	16758	89-04 bumper , radiator support to hood (adjustable) (w/ nut)	\$6.00
785	16758	89-04 bumper , radiator support to hood (adjustable) (w/o nut)	\$4.00
939	16758	79-93 rubber bumper , fender to hood (does 2 sides) (4)	\$4.00
940	16758	79-82 kit , hood bumpers (4 fender, 2 radiator support)	\$12.00
941	16758	83-93 kit , hood bumpers (4 fender, 2 radiator support)	\$16.00
286	16763	71-88 nut , adjustable hood bumpers (4)	\$6.00
381	16763	71-88 bumper , adjustable hood w/ nuts	\$6.00
1299	16796	79-82, 84-86 SVO bolts & nuts , hood hinge (does 2 sides) (8)	\$8.00
1300	16796	83-93 (EXC. Svo) bolts & nuts , hood hinge (does 2 sides) (8)	\$9.00
1260	16828	79-86 screw , hood prop rod anti-rattle clip	\$2.00
649	16826	75-78 clip , hood prop rod (does both ends of rod) (2)	\$4.00
786	16826	79-98 clip , hood prop rod	\$2.00

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
------	--------	-------------	-----

CHASSIS 17000-17999: *speedometer, wipers, washers, rear view mirrors, bumpers*

1150	17260	65-70 all, 79-93 w/man trans rubber grommet , speedometer cable at firewall	\$4.00
1202	17531	74-93 clip , windshield wiper linkage	\$3.00
652	17664	69-93 repair harness , windshield washer pump connector	\$9.00
893	17709	79-93 screw , inside mirror cover (2)	\$1.00
979	17698	91-95 bracket , rearview mirror mounting	\$4.00
1279	17756	74-76 retainer , front bumper molding (push in type) (6)	\$9.00
984	17835	79-93 retainer , rear bumper cover (6)	\$5.00
1257	17835	87-93 nut , rear bumper cover (10)	\$14.00
985	17835	94-98 retainer , rear bumper cover (7)	\$6.00
986	17835	99-04 retainer , rear bumper cover (5)	\$4.25

CHASSIS 18000-19999: *heater, radio, antenna, speaker, air conditioning, shock absorbers*

870	18813	79-83 screw , antenna base (4)	\$1.20
1305	18813	79-93 screw , antenna base (SS) (4)	\$2.00
872	18978	87-93 hatchback screw , rear speaker grille (w/ nuts) (8 of each)	\$8.00
894	18978	87-93 screw , door speaker grille (2)	\$1.00
780	19986	86/ repair harness , heater-A/C fan speed switch	\$11.00

BODY 00000-12999: *front body, floor pan, under body, cowl, dash panel*

1062	01610	79-84 rubber plug , center of firewall (1.75" hole)	\$1.75
1273	01816	15/ retainer , cowl vent (6)	\$10.00
989	02010	79-93 rubber plug , outer corner of cowl (under hood) (2)	\$4.00
990	02038	79-93 rubber plug , side of cowl (behind fender) (4)	\$6.00
867	02228	79-82 screw , cowl vent grille (7)	\$4.00
978	02228	79-82 grommet , grille retaining (2)	\$4.00
1304	02228	79-82 kit , cowl vent grille mounting (11)	\$8.00
868	02228	83-93 screw , cowl vent grille (6)	\$4.50
1070	02228	94-04 retainer , top cowl vent grille (3)	\$4.00
1121	02228	83-93 nut , cowl vent grille (4)	\$4.00
1122	02228	83-93 screw & nut , cowl vent grille (6 screws, 4 nuts)	\$8.50
856	02344	79-93 retainer , kick panel (used on drivers side) (2 5/8" long)	\$4.50
857	02344	79-93 retainer , kick panel (used on both sides) (1 1/4" long) (4)	\$6.00
858	02344	94/ retainer , kick panel (does 2 sides) (1 3/4" long) (2)	\$4.00
859	02344	79-93 kit , kick panel (does both sides, complete) (8)	\$12.00
899	02344	79-93 screw , kick panel (does 2 sides) (2)	\$1.00
967	02344	84-93 retainer , passenger side kick panel (1" diameter head) (1)	\$1.25
948	03012	79-93 coupe & hatch spacer , windshield glass (2)	\$10.00
880	03599	79-86 screw , door "A" pillar trim (2)	\$1.00
115	04115	65-78 rubber tip , sunvisor (2)	\$1.50
996	04144	84-93 hatchback & 84-04 coupe screw , sun visor retaining clip (2)	\$1.00
997	04144	85-86 coupe screw , sun visor retaining clip (2) (use part# 996)	n/a
998	04144	85-93 convertible screw , sun visor bracket (4)	\$1.20
892	04282	79-86 screw , dash pad (8)	\$2.40
1060	04424	87-93 clip , console shifter bezel (4)	\$4.00
888	04536	79-86 kit , console (26 screws, 2 nuts)	\$9.00
890	04567	79-86 screw , console coin tray (2)	\$1.00
1058	04786	87-93 rubber bumper , console mounted ashtray lid (4)	\$2.00
950	06010	79-86 rubber bumper , glove box (2)	\$1.50

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
------	--------	-------------	-----

BODY 00000-12999: front body, floor pan, under body, cowl, dash panel (continued)

951	06024	79-86 rubber bumper , console armrest (2)	\$1.50
952	06024	87-93 rubber bumper , console armrest (2)	\$1.50
1263	06024	87-93 clip , armrest assembly to console (2)	\$2.50
657	10000	65/ shim , body (4 - 1/16", 2 - 1/8")	\$3.00
1018	10108	01-04 Bullit and Mach I bolt , sub frame connectors (does 2 sides) (8)	\$10.00
1065	10124	79-93 rubber plug , frame rail just in front of rear tire (3/4" x 1" oval hole) (2)	\$2.00
873	10176	87-93 GT screw , side skirt and fender extension (42)	\$12.60
947	10176	99-04 retainer , rocker molding (does 2 sides) (14)	\$11.00
981	10176	94-04 retainer , rocker molding (does 1 side) (5)	\$2.50
956	10176	94-98 retainer , rocker molding (does 2 sides) (16)	\$8.00
1226	10176	94-98 kit , complete rocker molding mounting (50)	\$40.00
1294	10176	15/ kit , complete rocker panel/splitter mounting (does 1 side) (24)	\$29.00
1085	10214	87-93 GT rivet , body side ground effects mounting bracket (does 1 side) (22)	\$14.00
895	10000	79-93 kit , body plug (rubber) (30)	\$32.00
993	11135	79-93 rubber plug , floor pan under rear seat (2)	\$4.00
1063	11135	79-93 rubber plug , front floor pan just before rise (1" hole) (4)	\$3.50
1064	11135	79-93 rubber plug , floor pan under front seats (7/8" hole) (4)	\$2.50
994	11215	79-04 rubber plug , spare tire well drain (1)	\$1.00
596	11218	71-78 rubber plug , trunk floor hole (2)	\$3.00
992	11250	79-93 rubber plug , trunk floor drop (2)	\$2.00

BODY 13000-19999: floor mats, sill plates

666	13208	74-78 screw , sill plate (does 2 sides) (12)	\$3.00
667	13208	79-93 screw , sill plate (black, phillips oval head) (does 2 sides) (8)	\$2.50
668	13208	79-93 screw , sill plate (chrome, phillips oval head) (does 2 sides) (8)	\$2.50
889	13208	79-93 screw , sill plate (black phillips pan head) (does 2 sides) (8)	\$2.40
901	13208	79-93 screw , sill plate (chrome phillips pan head) (does 2 sides) (8)	\$2.40
871	13530	87-93 screw , console arm rest repair panel (4)	\$1.20

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
BODY 20000-39999: <i>body side, doors, windows, regulators</i>			
1076	20124	94-04 nylon plug , trailing edge of door (does 1 door) (2)	\$2.00
1077	20124	94-04 rubber plug , trailing edge of door (1/4" hole) (does 2 doors) (2)	\$2.00
1105	20908	87-93 clip , outside belt molding (does 2 sides) (8)	\$6.00
977	21060	79-80 all, 83-86 convertible retainer , belt molding on door (7)	\$7.00
1262	21060	79-82 all, 83-86 convertible retainer & nuts , belt molding on door (14)	\$11.00
1056	21410	79-93 kit , door glass to channel bracket mounting (does 1 window) (6)	\$8.00
881	21456	79-93 screw , inside door belt weatherstrip (SS) (12)	\$4.50
1068	21842	79-93 rivet , door lock actuator	\$3.50
1180	21842	99-04 repair harness , door lock actuator	\$14.00
650	22008	83-89 door lock striker bolt assembly	\$12.00
931	22008	71-93 bushing , door latch striker, 81-91 hatch latch striker (1)	\$2.50
932	22008	71-78 striker bolt assembly, door latch (1)	\$15.00
918	22152	79/ clip , door latch rod end retainer (1)	\$1.50
787	22404	79-93 rivet , exterior door handle (does 1 handle) (2)	\$2.50
466	22600	67-78 screw , door & window handle (4)	\$1.50
1280	22600	74-76 handle , inside door release	\$10.00
891	22634	79-93 screw , door handle bezel (2)	\$1.00
657	10000	65/ shim , body (4 - 1/16", 2 - 1/8")	\$3.00
729	22800	69-78 bolt , door hinge (does 1 door) (12)	\$10.00
682	22811	79-93 kit , door hinge pin (w/ cotter pins & bushings) (one door) (8)	\$8.00
1019	22811	79-93 kit , door hinge pin and oversize bushings for repair (does 1 hinge) (4)	\$5.00
1160	23240	73-93 roller , door glass	\$6.00
653	23342	79-86 handle , window crank (w/ black knob)	\$9.00
976	23342	79-86 handle , window crank (black)	\$9.00
1281	23342	74-78 handle , window regulator	\$12.00
919	23424	71-93 gear assembly, power window motor repair (all exc. rear windows: convertible)	\$19.00
920	23424	71-93 torque pin , power window motor repair (does 1 motor) (3)	\$5.00
971	23942	79-93 clip , door panel retaining (does 1 door) (12)	\$7.80
1163	23942	94-04 retainer , door panel (2)	\$1.50
1203	24100	81-86 screws , armrest (on door) (does 2 sides) (6)	\$4.00
927	24140	87-93 nut , armrest (at top of hand grip)	\$1.50
1176	24144	87-93 screws , armrest (on door) (does one side) (4)	\$2.00
1184	24144	87-93 nuts , armrest to door (does one side) (4)	\$4.00
1185	24144	87-93 nuts & screws , armrest to door (does one side) (8)	\$5.00
199	26528	69-78 rubber bumper , door (2)	\$2.00
1288	31012	94-98 retainer , interior quarter trim & quarter window trim (does 2 sides) (10) see 52018	\$10.00

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
------	--------	-------------	-----

BODY 40000-41999: rear body - quarter panel - trunk area - hatch

926	40110	79-90 rubber bumper , rear hatch (2)	\$7.00
955	40110	79-93 coupe & convertible rubber bumper , trunk lid (2)	\$2.00
988	40110	79-93 hatchback rubber plug , bottom (rear) corners of hatch (large oval) (2)	\$9.00
991	40320	79-93 rubber plug , taillight panel (behind bumper cover) (2)	\$2.00
953	40526	79-93 rubber bumper , gas filler door (2)	\$2.00
999	40544	79-04 kit , license plate screws and nuts (OEM style, black screws) (6)	\$4.00
1000	40544	79-04 kit , license plate screws and nuts (stainless steel screws) (6)	\$4.50
1179	40544	05/ kit , license plate mounting (OEM style screws) (8)	\$5.00
1182	40544	05/ kit , license plate mounting (SS screws) (8)	\$6.00
1292	42410	87-93 hatchback screws , interior hatch upper cover (4)	\$3.00
1071	45455	79-93 coupe screw rivet , trunk liner (8)	\$6.00
1075	45455	83-93 convertible screw rivet , trunk liner (6)	\$4.50

BODY 42000-49999: exterior trim, window molding clips, rear wing, locks, key blanks

936	42413	79-93 coupe clip , rear window top & vertical moldings (14)	\$4.00
938	42413	79-93 coupe & hatch clip , windshield molding (13)	\$3.75
942	42413	65-93 rivet , window molding clips (to replace broken studs) (10)	\$4.00
1244	42413	65-93 screw , replaces welded stud for molding clips (12)	\$4.00
1004	42413	79-93 hatchback clip , rear window molding (does whole window) (22)	\$38.00
1005	42413	79-93 coupe kit , rear window molding clips (does whole window) (19)	\$14.00
1006	42413	79-93 coupe clip , rear window bottom molding (5)	\$10.00
1011	42413	79-93 hatchback clip , front and rear window molding (35)	\$39.00
1012	42413	79-93 coupe clip , front and rear window molding (32)	\$18.00
611	43562	67-93 set, ignition & trunk key (original factory style)	\$10.00
916	43562	94-96 key blank, (10 cut) (1)	\$6.00
917	43562	96/ key blank, (8 cut, non-"PATS") (1)	\$4.50
883	44210	84-85 hatchback screw , rear wing (2)	\$1.50
884	44210	86-93 hatchback screw , rear wing (4)	\$2.10
885	44210	84-85 SVO screw , rear wing (4)	\$3.00
886	44210	86 SVO screw , rear wing (6)	\$3.60
1205	44210	96-98 Cobra hole plug , for spoiler delete (4)	\$3.00

BODY 50000-59999: roof, T-top, convertible top

903	50000	81-88 screw , T-Top trim cap (12)	\$3.60
879	51726	79-86 screw , roof rail molding retainer (2)	\$1.00
1288	52018	94-98 retainer , interior quarter trim & quarter window trim (does 2 sides) (10) see 31012	\$10.00
1167	53712	79-93 clip , sunroof retaining (w/ screws, washers) (does 2 sides) (2 of each) (SS)	\$32.00
1278	51916	76-78 clip , headliner wire (5)	\$6.00
1282	51916	79-93 retainer , headliner (4)	\$3.00
1067	55150	86-93 rivet , deck lid mounted luggage rack (10)	\$10.00

BODY 60000-67599: interior trim screw kits

861	60000	79-86 hatchback kit , interior screw (does complete interior) (boxed) (190)	\$74.00
862	60000	87-93 hatchback kit , interior screw (does complete interior) (boxed) (158)	\$68.00
863	60000	83-86 convertible kit , interior screw (does complete interior) (boxed) (165)	\$60.00
864	60000	87-93 convertible kit , interior screw (does complete interior) (boxed) (120)	\$44.00
865	60000	79-86 coupe kit , interior screw (does complete interior) (boxed) (135)	\$48.00
866	60000	87-93 coupe kit , interior screw (does complete interior) (boxed) (92)	\$38.00

Prices shown are suggested retail prices (SRP) - Dealer discount to be applied

Kit#	Group#	Description	SRP
BODY 60000-67599: <u>interior, seats</u>			
168	60000	65/ hog ring , upholstery (50)	\$1.50
431	60000	65/ hog ring , upholstery (500)	\$10.00
874	60230	83-89 convertible screw , seat belt bezel (6)	\$2.00
970	60230	90-93 convertible clip , front shoulder belt bezel (at quarter trim) (2)	\$2.50